7853448398 \* 60cp \* 01/24/2003 13:14 コロロエニ 11 59 16:46 FRCM: LUCO COMPLIANCE DEPT 541-343-6376

TO:7283458591

23802-1004

FRIAL SAPATY DATA SHEET

E-6000 LV CLEAR (NON-FLAM)

Pagor

PRODUCT NAME: E-6000 LV CLEAR (NON-FLAM)

HMIS CODES: H F R

PRODUCT CODE: 371000132

3 \* 0 1 :

MANAGETARAGE MOSSAGES SECTION 1 - MANUFACTURER IDENTIFICATION SERVED REGESTED DESERT

ADDRESS

MANUPACTURER'S NAME: ECLECTIC PRODUCTS, INC. : 995 SOUTH A STREET SPRINGFIELD, OR 9 97477

DATE REVISED 1 5/20/97

EMERGENCY PHONE

(800) 535-5053 £

DATE PRINTED : 03/18/99

NAME OF PREPARER I MSDS/COMPLIANCE DEP'

: (800) 757-4667 INFORMATION PHONE

www.medwaum SECTION 2 - HAZARDOUS INGREDIENTS/BARA III INFORMATION ############

REPORTABLE COMPONENTS

CAS BESIDER \_\_\_\_\_\_

VAPOR PRESCRIP ON THE B TROOP

WEIGHT PROCEST

TETRACHLOROETHYLENE (PEXCHLOROETHYLENE)

127-13-4 13

SS DEG F 71

ACGIH TLV: TWA=25 ppm (170 mg/m3); STEL=100 ppm (685 mg/m3)

OSHA PZL: TWA=100 ppm; CEILING=200 ppm

\* Indicates toxic chemical(s) subject to the reporting requirements of section 313 of Title III and of 40 CFR 372.

PROPOSITION 65 STATEMENT: This product contains a chemical known to the state of California to 4 DOT CLASS: 5MALL PKG. - CONSUMER COMMODITY ORM-D: 1 GA. & LARGER. cause cancer. TETRACHLOROETHYLENE MIXTURE, 6.1, UN 1897, PG III

PEGASSESSANTESSANTE SECTION 3 - PHYSICAL/CHEMICAL CHARACTERISTICS GERMANDERSE

BOILING RANGE: >250 DEG F VAPOR DENSITY: Heavier than air. SPECIFIC GRAVITY (H20-1): MATERIAL VOC: 0.01 lb/gl

EVAPORATION RATE: Slower than ether. SOLUBILITY IN WAT APPEARANCE AND ODOR: Viscous liquid with ether-like odor.

SOLUBILITY IN WATER: Negligible

VOC calculations are based on the federal EFA definition of volatile organic compound under the Clean Air Act. State and local air quality authorities may have more stringent regulation.

EXELECTION 4 - FIRE AND EXPLOSION HAZARD DATA EXECUTED NAMES

METROD USED: N/A FLASH POINT: None PLAMMABLE LIMITS IN AIR BY VOLUME - LOWER: N/A UPPER: N/A

EXTINGUISHING MEDIA: Foam, CO2, Dry Chemical, Water Fog

SPECIAL FIREFIGHTING PROCEDURES

I. Hear positive pressure salf-contained breathing apparatus (SCBA). II. Cool fire exposed containers with water.

UNUSUAL FIRE AND EXPLOSION HAZARDS

Product is non-flammable and non-explosive under normal conditions of use. At high temperatuproduct decomposes to give off hydrochloric acid as 54s plus other toxic and irritating vapors

Page 1 of 4

Item Numbers: 23802-1004

01/24/2003 13:14 7083440390 ے۔ لایال AUG-11 99 16:47 FROM: WUCD COMPLIANCE DEPT 541-343-6376

TO: 7083458591

# MATERIAL SAFETY DATA SKEET

(NON-FLAM) E-6000 LV CLEAR

Page: 2

auch as phosgene and chlorine. If storage containers are exposed to excessive heat, overpressurization can result in container rupture.

MINICIPAL TO THE REPORT OF THE PROPERTY OF THE

STABILITY: Stable CONDITIONS TO AVOID

Avoid extreme heat, flame or sparks.

INCOMPATIBILITY (MATERIALS TO AVOID)

Strong acids and oxidizing materials. Avoid mixing with caustic sods or potash.

#### HAZARDOUS DECOMPOSITION OR BYPRODUCTS

I. Toxic/irritating gases and fumes. II. Hydrogen chloride, CO2, Simple Hydrocarbons, Phosgene and Chlorine.

HAZARDOUS POLYMERIZATION: Will not occur.

# SERECTION 6 - HEALTH HASARD DATA DEEDSODDEEDSEEDSODDEEDS

#### INHALATION HEALTH RISKS AND SYMPTOMS OF EXPOSURE

Dissiness may occur at 200 PPM; progressively higher levels can cause irritation of the respiratory tract, drunkeness, naussa, incoordination, unconsciousness and even asphyxiation in confined poorly ventilated areas. Overexposure can cause CNS damage.

# SKIN AND BYE CONTACT HEALTS RISKS AND SYMPTOMS OF EXPOSURE

EYES. Product in eyes can result in discomfort, pain and irritation. Vapors may irritate the eyes at about 100 PPM. SKIN: Irritation can develop following repeated and/or prolonged contac and may cause drying or flaking of skin.

# SKIN ABSORPTION HEALTH RISKS AND SYMPTOMS OF EXPOSURE

A single prolonged exposure is not likely to result in material being absorbed through the skin in harmful amounts. The LD50 of tetrachloroethylene for skin absorption in rabbits is >10,000 mg/kg.

#### INGESTION HEALTH RISKS AND SYMPTOMS OF EXPOSURE

Single dose oral toxicity is low. Ingestion may result in irritation of the mouth and gastrointestinal tract along with other effects as listed above for inhalation. Vomiting and subsequent aspiration into the lungs may lead to injury of other body systems.

### HEALTH HAZARDS (ACUTE AND CHRONIC)

Tetrachloroethylene has been shown to increase rate of spontaneously occuring malignant tumors in certain lab rate and mice. Other long-term inhalation studies in rate failed to show tumorigenic response. Epidemiology studies are limited and have not established an association between tetrachlorosthylene exposure and cancer. Did not cause birth defects in animals. Birth defects unlikely. Prolonged exposure above OSHA permissible limits may result in liver and kidney damaga.

CARCINOGENICITY: NTP CARCINGGEN: Yes IARC MONOGRAPHS: Yes OSHA REGULATED: No TETRACHLOROETHYLENE IS LISTED AS POTENTIAL CARCINOGEN BY LARC & NTP. REBULTS OF IN VITRO MUTAGENICITY TESTS HAVE BEEN NEGATIVE. PRUDENT HANDLING PRACTICES SHOULD BE FOLLOWED TO MINIMI? HUMAN EXPOSURE.

MEDICAL CONDITIONS GENERALLY AGGRAVATED BY EXPOSURE

Page 2 of 4

Item Numbers: 23802-1004

01/24/2003 13:14 7083440390 JUDIE AUG-11 99 16:47 FROM: WUCD COMPLIANCE DEPT 541-343-6376

TO:7083458591

# MATERIAL SAFETY DATA SHEET

E-5000 LV CLEAR (NON-FLAM)

Pagei

Pre-existing eye, skin, and lung conditions.

#### EMERGENCY AND FIRST AID PROCEDURES

TYES: Flush with water for at least 15 minutes, seek medical care if irritation persists or develops. SKIN: Wipe from skin and wash with soap and water. If irritation develops seek medical attention. INHALATION: Remove to fresh air. If breathing is difficult, give exygen. Give artificial resuscitation if not breathing. INGESTION: Do not induce vomiting. Call a physician. Give 1 or 2 glasses of water to drink. \*\*\* See note to physician under "Other Precautions".

#### DESCRIPTION 7 - PRECAUTIONS FOR SAFE HANDLING AND USE DESCRIPTIONS IN

#### STEPS TO BE TAKEN IN CASE MATERIAL IS RELEASED OR SPILLED

I. SMALL LEAKS: Wipe up, or sosk up immediately with inert material. Remove to outdoors. II. LARGE SPILLS: Evacuate area; contain liquid; transfer to closed metal containers; keep out of water supply.

#### WASTE DISPOSAL METHOD

I. Reclaim or incinerate the non-hardened product. II. Material resulting from clean up operations may be hazardous waste and therefore, subject to specific regulations. Dispose of i accordance with local, state and federal regulations at time of disposal.

#### PRECAUTIONS TO BE TAKEN IN HANDLING AND STORING

In large quantities, lethal concentrations may exist in areas with poor ventilation. Do not use in poorly ventilated or confined spaces without proper respiratory protection. Vapors will collect in low places such as pits, storage tanks and other confined spaces. Do not enter these areas unless special breathing apparatus is used and an observer is present.

#### OTHER PRECAUTIONS

\*\*\* NOTE TO PHYSICIAN: Because rapid absorption may occur through lungs if aspirated and cause systemic effects, the decision of whether to induce vomiting or not should be made by physician If lavage is performed, suggest endotracheal and/or esophagal control. Danger from lung aspiration must be weighed against toxicity when considering emptying the stomach. Do not administer sympathomimetic drugs unless absolutely necessary. No specific antidote. Supportive care. Treatment based on judgement of the physician in response to reactions of the patient.

# THE STREET STREET SECTION 8 - CONTROL MEASURES SECRETARISHED SECRETARISH

#### RESPIRATORY PROTECTION

I. If ventilation is inadequate to maintain atmospheric levels below the TLV wear a NIOSH approved air purifying organic cartridge respirator. II. For amergency and over exposure, use an approved positive pressure self-contained breathing apparatus. III. In confined or poorly ventilated areas, use an approved positive pressure self-contained breathing apparatus.

#### **VENTILATION**

Adequate vantilation should be provided to keep vapor concentrations below acceptable exposure guidelines. Use only with adequate ventilation.

#### PROTECTIVE GLOVES

Gloves are recommended. Neoprene-latex gloves have been used satisfactorily.

#### KYE PROTECTION

splashproof goggles. Only required if handling poses a risk of eye contact.

Page 3 of 4

01/24/2003 13:14 7083440390 **JUDITE** AUG-11 99 16:48 FROM: WUCO COMPLIANCE DEPT 541-343-6376

TO:7083458591

# MATERIAL SAFETY DATA SERET

(NON-FLAM) H-6000 LV CLEAR

Page:

OTHER PROTECTIVE CLOTHING OR EQUIPMENT

As necessary to prevent skin contact. Selection of specific items such as gloves, boots, apron or full body suit will depend on operation. Work station conditions should be evaluated by management to determine proper personal protection.

WORK/RYGIENIC PRACTICES

Do not allow eye or skin contact. Avoid breathing vapors. Wash thoroughly after handling and before esting or drinking.

To the best of our knowledge, the information provided herein is accurate, obtained from source believed to be accurate. Since the conditions and mathods of use of our product are beyond our control. We disclaim any and all liability arising out of the improper use of this product or the information provided herewith.

Page 4 of 4