SHENZHEN WINGART ART SUPPLIES CO., LTD

WingArt[®]

Qiping Industrial Zone, Guihua Village, Guanlan Town, Shenzhen, China

TEL: 0755-27520848 27520858 FAX: 0755-2750878

MATERIAL SAFETY DATA SHEET

DATE OF ISSUE: Jan.01. 2016

1. IDENTIFICATION OF THE SUBSTANCE / PREPARATION AND OF THE COMPANY / UNDERTAKING

1.1 IDENTIFICATION OF THE SUBSTANCE OR PREPARATION

PRODUCT NAME	Washable Paint
FORMULA	Not applicable (mixture)
CAS # AND NAME	Not applicable (mixture)

1.2 COMPANY IDENTIFICATION

SHENZHEN WINGART ART SUPPLIES CO., LTD. QIPING INDUSTRIAL PARK, GUIHUA VILLAGE, GUANLAN TOWN, SHENZHEN, GUANGDONG, P.R.C. TEL: 86 755 2752 0858 FAX: 86 755 2752 0878

2. COMPOSITION / INFORMATION ON INGREDIENTS

Ingredient	Concentration	CAS No.	Hazard
Water	61.5	7732-18-5	None
Calcium Carbonate	26.0	471-34-1	None
Preservative	0.1	N/A	None
Disperser	0.65	N/A	None
CMC	3.2	9004-32-4	None
Pigment	1.55	N/A	None
Starch	7	9005-25-8	None

3. HAZARDS IDENTIFICATION

3.1. HEALTH HAZARD DATA3.1.1. EFFECTS OF A SINGLE OVEREXPOSURESwallowingNo evidence of harmful effects from available information.

Page 1 of 7

SHENZHEN WINGART ART SUPPLIES CO., LTD



Qiping Industrial Zone, Guihua Village, Guanlan Town, Shenzhen, China

TEL: 0755-27520848 27520858 FAX: 0755-2750878

MATERIAL SAFETY DATA SHEET

DATE OF ISSUE: Jan.01. 2016

Skin absorption No evidence of harmful effects from available information.

Inhalation

Trace component and residual monomer powder may be irritating to the eyes, mucous membrane, respiratory tract, and may produce symptoms of headache, nausea in poorly ventilated areas.

Skin contact Prolonged contact may cause transient reddening of the skin.

Eye contact Direct contact may cause eye irritation.

3.1.2. EFFECTS OF REPEATED OVEREXPOSURE No evidence of harmful effects from available information.

3.1.3. MEDICAL CONDITIONS AGGRAVATED BY OVEREXPOSURE

A knowledge of the available toxicology information and of the physical and chemical properties of the matter suggests that overexposure is unlikely to aggravate existing medical conditions.

3.1.4. OTHER EFFECTS OF OVEREXPOSURE No evidence of harmful effects from available information.

4. FIRST AID MEASURES

4.1. SWALLOWING No harmful effects expected.

4.2. INHALATION No emergency care anticipated.

4.3. SKIN CONTACT

Wash skin with soap and water until water is no longer cloudy. If clothing is soaked, remove and wash before reuse.

Page 2 of 7

SHENZHEN WINGART ART SUPPLIES CO., LTD



Qiping Industrial Zone, Guihua Village, Guanlan Town, Shenzhen, China

TEL: 0755-27520848 27520858 FAX: 0755-2750878

MATERIAL SAFETY DATA SHEET

DATE OF ISSUE: Jan.01. 2016

4.4. EYE CONTACT

Immediately flush eyes with plenty of water. Get medical attention if irritation persists.

4.5. NOTES TO PHYSICIAN

Toxicology studies have shown this or similar material to be of very low acute toxicity. There is no specific antidote. Treatment of overexposure should be directed at the control of symptoms and the clinical condition of the patient.

5. FIRE-FIGHTING MEASURES

5.1. EXTINGUISHING MEDIA This product is a non-flammable mixture.

5.2. EXTINGUISHING MEDIA TO BE AVOIDED None.

5.3. SPECIAL FIRE FIGHTING PROCEDURES None.

5.4. SPECIAL PROTECTIVE EQUIPMENT FOR FIREFIGHTERS Use self-contained breathing apparatus when fighting fires in enclosed areas.

5.5. UNUSUAL FIRE AND EXPLOSION HAZARDS

Product will not burn but may spatter if temperature exceeds boiling point of water. Dried solids can burn giving off oxides of carbon.

6. ACCIDENTAL RELEASE MEASURES

Steps to be taken if material is released or spilled Restrict the area to only those personnel needed. Major spills should be collected for disposal. Minor spills may be flushed to sewer if permitted by national, state and local regulations.

7. HANDLING AND STORAGE

7.1. HANDLING

Page 3 of 7

SHENZHEN WINGART ART SUPPLIES CO., LTD



Qiping Industrial Zone, Guihua Village, Guanlan Town, Shenzhen, China

TEL: 0755-27520848 27520858 FAX: 0755-2750878

MATERIAL SAFETY DATA SHEET

DATE OF ISSUE: Jan.01. 2016

<u>General handling precautions</u> Avoid breathing powders in top of shipping container. Use with adequate ventilation. Avoid contact with skin and clothing. Wash thoroughly after handling. <u>Ventilation</u> General (mechanical) room ventilation is expected to be satisfactory. Use local exhaust if needed to control mist and vapours.

Other precautions None known.

7.2. STORAGE Keep container closed when is not used.

8. EXPOSURE CONTROLS / PERSONAL PROTECTION

8.1. EXPOSURE LIMITS Not Applicable.

8.2. PERSONAL PROTECTION

<u>Respiratory protection</u> None should be required. If necessary, use OSHA/NIOSH- approved respirators in poorly ventilated areas.

<u>Hand protection / protective gloves</u> Use gloves impervious to water and soap.

Eye protection Safety glasses

Other protective equipment Eye bath and safety shower.

9. PHYSICAL AND CHEMICAL PROPERTIES

PHYSICAL STATE

Fluid

Page 4 of 7

Item Numbers: 64253-1009

Page 4 of 7

SHENZHEN WINGART ART SUPPLIES CO., LTD

WingArt[®]

Qiping Industrial Zone, Guihua Village, Guanlan Town, Shenzhen, China

TEL: 0755-27520848 27520858 FAX: 0755-2750878

MATERIAL SAFETY DATA SHEET

DATE OF ISSUE: Jan.01. 2016

ODOUR	Mild
MOLECULAR WEIGHT	Mixture
BOILING POINT	100°C
FREEZING POINT	0°C
MELTING POINT	Not Applicable
FLASH POINT	Not Applicable (aqueous system)
FLAMMABILITY LIMITS	LOWER: Not Applicable (aqueous system)
IN AIR (% by Volume)	UPPER: Not Applicable (aqueous system)
SPECIFIC GRAVITY (H20=1)	1.1
VAPOUR PRESSURE	Same as water
VAPOUR DENSITY (air=1)	<1
EVAPORATION RATE	Is slower than Butyl Acetate (Butyl acetate $= 1$)
SOLUBILITY IN WATER	Dilutable
PERCENT VOLATILES	50Wt %(Water)

10. STABILITY AND REACTIVITY

10.1. STABILITY Stable.

<u>Conditions to avoid</u> None.

Incompatible materials None.

<u>Hazardous combustion products</u> Carbon monoxide and/or carbon dioxide.

10.2. POLYMERIZATION Will not occur.

Conditions to avoid None.

11. TOXICOLOGICAL INFORMATION

Page 5 of 7

SHENZHEN WINGART ART SUPPLIES CO., LTD



Qiping Industrial Zone, Guihua Village, Guanlan Town, Shenzhen, China

TEL: 0755-27520848 27520858 FAX: 0755-2750878

MATERIAL SAFETY DATA SHEET DATE OF ISSUE: Jan.01, 2016

11.1. ACUTE TOXICOLOGICAL INFORMATION Information on analogous product shows minimal toxicity concerns.

11.2. OTHER TOXICOLOGICAL INFORMATION

Information on analogous product shows minimal toxicity concerns.

11.3 ADDITIONAL INFORMATION None

12. ECOLOGICAL INFORMATION

12.1. PERSISTENCE AND DEGRADABILITY Polymer is not biodegradable.

12.2. ENVIRONMENTAL RISKS Not toxic to fish or plants.

12.3. OTHER INFORMATION

Does not inhibit bacteria in waste treatment facilities.

13. DISPOSAL CONSIDERATIONS

WASTE DISPOSAL METHOD(S) Recycle or incinerate or absorb water and bury in a suitable landfill where permitted under appropriate national and local regulations.

14. TRANSPORT INFORMATION

TRANSPORT CLA ADR/RID	ASSIFICATION This product is not submitted to the ADR regulations.
IMDG	This product is not submitted to the IMO regulations.
MARPOL	ANNEX II: Not evaluated at this moment. ANNEX III: Not classified.

Page 6 of 7

SHENZHEN WINGART ART SUPPLIES CO., LTD



Qiping Industrial Zone, Guihua Village, Guanlan Town, Shenzhen, China

TEL: 0755-27520848 27520858 FAX: 0755-2750878

MATERIAL SAFETY DATA SHEET DATE OF ISSUE: Jan.01. 2016

ICAO This product is not submitted to the ICAO regulations.

15. REGULATORY INFORMATION

All other national and local regulations, if applicable to the use, transport or disposal of this product, should be observed.

16. OTHER INFORMATION

RECOMMENDED USES AND RESTRICTIONS Please consult the relevant product and/or application information for this product.

REVISED SECTIONS IN THIS ISSUE: All sections in this issue have been revised.

All sections in this issue have been revised.

Copyright 2016

The information herein is given in good faith and to the best of our knowledge but no warranty, expresses or implies, is made.

Page 7 of 7